











Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

**Position**

- 1 = A 960 876 XX
- 2 = A 963 309 NU
- 3 = A 963 877 NU
- 4 = A 963 372 NU
- 5 = A 960 363 XX
- 6 = A 961 667 NU (2x)
- 8 = A 962 715 NU
- 9 = A 962 716 NU  
A 962 985 NU (CLICK)
- 11 = A 962 848 NU (2x)
- 12 = A 963 495 NU (2x)
- 14 = A 963 361 NU
- 15 = A 960 321 XX
- 17 = A 963 507 NU
- 20 = A 962 370 NU
- 21 = A 960 368 NU
- 22 = A 960 367 XX
- 23 = A 962 138 NU
- 24 = A 963 404 NU
- 25 = A 961 230 XX
- 26 = A 962 385 XX
- 27 = A 960 197 NU
- 28 = A 960 196 NU




XX = AA, AD...



**MOMENTS**


A 3903 .. A 3905 .. A 3906 .. A 4789 ..  
 A 3909 .. A 3926 .. A 4104 .. A 5565 ..  
 A 5566 ..













0811 / A 865 523  
 (+ A 865 612)  
 Made in Germany



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

www.idealstandardinternational.com





	<b>P</b>	<b>bar</b>		MAX. 10		5		<b>Q</b> (3 bar)
	<b>T</b>	<b>°C</b>		MAX. 80		65		<b>l/min</b>
						40		<b>13</b>