



A962568NU




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto / Parte de reposição / Reservonderdelen / Reservdelar / Reservdeler / Varaosat / Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely / Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieśe de schimb / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



1	A 962 872 AA	12	A 962 568 NU	22	A 961 073 AA
3	A 962 998 NU	14	A 962 529 NU	25	A 960 400 AA
4	A 962 870 AA	15	A 961 332 NU	28	A 860 780 AA
5	A 962 871 AA	18	A 962 594 NU	30	A 860 778 NU
6	A 963 427 NU	19	A 961 810 NU	31	A 860 874 AA
7	A 962 229 NU	20	A 962 595 NU	33	A 860 807 AA
8	A 962 230 NU	21	B 960 242 AA	34	B 9442 AA
9	A 963 432 NU			35	F 960 891 AA
10	A 962 563 NU			36	A 860 873 AA




XX = AA, AD...



## CERATHERM 100


A 5778 .. A 5955 ..







0215 / A 866 489 40  
(+ A 865 612)  
Made in Germany



Ideal Standard International BVBA  
Corporate Village - Gent Building  
Da Vincilaan 2  
1935 Zaventem  
Belgium

www.idealstandardinternational.com





<b>P</b> bar	0,5	MAX. 10	5	<b>Q</b> (3 bar) l/min
	<b>T</b> °C	MAX. 80	65 55	
				11
				20