






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD...

Position


- 4 = A 963 523 NU
- 5 = A 961 667 NU
- 6 = A 963 412 NU
- 8 = A 961 155 NU
- 9 = A 960 500 NU
- 10 = A 860 700 NU
- 11 = A 963 783 NU
- 17 = A 963 524 NU
- 19 = A 963 526 NU
- 21 = A 960 807 XX
- 22 = A 963 309 NU
- 23 = A 963 054 NU
- 24 = A 963 844 XX
- 26 = A 961 636 LJ
- 28a = A 960 620 XX
- 30 = A 963 176 NU
- 31 = A 963 441 NU
- 32 = A 963 444 NU
- 33 = A 963 442 XX
- 34 = A 963 443 NU
- 35 = A 963 571 XX
- 36 = A 963 542 NU
- 37 = A 963 891 XX



**CERAMIX**  
 A 5029 ..



1111 / A 965 756  
 (+ A 865 612)  
 Made in Germany



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

www.idealstandardinternational.com

