


Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto / Parte de reposição / Reserveonderdelen / Reservdelar / Reservdeler / Varaosat / Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely / Nadomestni deli / Резервни части / Zapczęści / Części Zapasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu


| Pos. | Part No.     |
|------|--------------|
| 1    | F 961 115 AA |
| 2    | F 961 116 AA |
| 3    | A 961 095 NU |
| 4    | A 861 298 NU |
| 7    | A 963 427 NU |
| 8    | A 962 229 NU |
| 9    | A 962 230 NU |
| 10   | A 963 432 NU |
| 11   | A 962 563 NU |
| 13a  | A 962 568 NU |
| 14   | A 962 529 NU |



|     |              |
|-----|--------------|
| 15  | A 961 332 NU |
| 18a | A 961 810 NU |
| 18b | F 960 894 NU |
| 20  | A 962 594 NU |
| 22  | A 962 595 NU |
| 23  | B 960 242 AA |



|    |              |
|----|--------------|
| 24 | B 961 042 AA |
| 25 | A 963 651 NU |
| 27 | A 860 933 NU |
| 28 | A 861 117 AA |
| 29 | A 963 173 NU |
| 30 | B 9403 AA    |

|    |              |
|----|--------------|
| 31 | F 960 891 AA |
| 33 | F 961 146 AA |
| 34 | A 1533 AA    |
| 35 | A 860 873 AA |
| 36 | B 1364 AA    |
| 37 | A 861 144 AA |



**CERATHERM 100**  
A 6290 ..

0918 / A 866 892  
(+ A 865 612)  
Made in Germany



Ideal Standard International NV  
Corporate Village - Gent Building  
Da Vincilaan 2  
1935 Zaventem  
Belgium

www.idealstandardinternational.com

