



Sparepart / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat / Vraosat /
 Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely / Nadomestni deli
 / Резервни части / Запчасти / Części Zapasowe / Piese de schimb / Rendelhető alkatrészek
 / Зпасні частини / Reservni delovi / Резервни делови / Резервни делови / Atsarginių
 dalių / Tellitavad varuosad / Rezervju daļu



Position

- 1 = A 961 491 AA
- 2 = A 963 667 NU
- 3 = A 961 484 NU
- 4 = A 963 372 NU
- 5 = A 961 492 AA
- 6 = A 961 638 NU
- 7 = A 963 022 NU
- 8 = A 962 715 NU
- 9 = A 960 145 NU
- 12 = A 961 493 NU
- 13 = A 963 157 NU
- 14 = A 960 205 NU
- 15 = A 961 182 NU (2x)
- 16 = A 960 133 NU





Jasper Morrison

E6415..










0811/ A 865 650
 (+ A865 612)
 Made in Europe



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





	P	bar				Q (3 bar)
	T	°C				l/min 23

