




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat / Vraosat / Varahlutir /
 Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely / Nadomestni deli / Резервни части / Запчасти
 / Części Zapasowe / Pieśe de schimb / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни
 делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi



Position



- | | |
|------------------------|-------------------|
| 1 = A 860 425 AA | 12 = A 960 587 NU |
| 3 = A 860 455 AA | 13 = A 960 588 NU |
| 4 = A 962 998 NU | 14 = A 960 589 NU |
| 5 = A 860 454 AA | 15 = A 961 665 NU |
| 6 = A 960 045 AA | 16 = A 860 415 NU |
| 7 = A 961 957 NU(3St.) | 18 = A 960 462 NU |
| 8 = A 963 425 NU | 19 = A 963 432 NU |
| 9 = A 961 623 NU | 20 = A 963 510 NU |
| 10 = A 963 426 AA | 23 = A 963 434 NU |
| 11 = A 963 427 NU | |



ACTIVE
A 4105 AA









0811 / A 865 699
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





| | | | | | | | | |
|--|----------|-----|--|---------|--|----------|--|-------------------------|
| | P | bar | | MAX. 10 | | 5 | | Q (3 bar) |
| | T | °C | | MAX. 80 | | 65 40 | | |