





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

xx = AA,AD,..




Position

- 1 = A 962 068 XX
- 2 = A 963 667 NU
- 3 = A 963 751 NU
- 4 = A 961 485 XX
- 5 = A 961 667 NU
- 7 = A 962 715 NU
- 8 = A 963 372 NU
- 9 = A 962 985 NU
- 11 = A 962 080 XX
- 12 = A 960 191 NU
- A 960 196 NU
- 14 = A 960 001 NU
- 15 = A 962 081 XX
- 16 = A 962 082 NU
- 17 = A 963 404 NU
- 18 = B 960 853 XX




MELANGE
A 4261.. A 5399 ..





0811/ A 865 812 40
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





	P	bar	MIN. 0,1			MAX. 5
	T	°C		MAX. 80		65
						40