





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX= AA,AD,..



Position

- 1 = A 962 052 XX
- 2 = A 962 053 XX
- 3 = A 960 396 XX
- 4 = A 961 268 NU (2x)
- 5 = A 960 445 NU
- 6 = A 961 864 XX
- 7 = A 962 574 NU
- 8 = A 962 335 NU
- 9 = A 960 462 NU
- 12 = A 961 010 NU
- 13 = A 963 026 NU
- 15 = A 960 113 XX
- 16 = A 960 111 AT
- 17 = A 962 227 XX
- 18 = A 961 807 NU
- 20 = A 961 798 NU
- 21 = A 960 110 XX
- 23 = A 961 811 NU
- 24 = A 961 810 NU
- 26 = A 961 816 NU
- 27 = A 963 028 NU
- 28 = A 963 030 NU
- 29 = A 963 090 NU
- 31 = A 961 817 NU (5x)
- 32 = H 960 184 NU
- A 962 594 NU (2x)
- 33 = H 960 185 NU
- 34 = H 960 440 XX
- 35 = A 962 061 XX
- 36 = A 960 239 NU
- 37 = B 960 578 XX




MELANGE
A 4335 ..





0811 / A 865 876
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





	P	bar		0,5			Q (3 bar)
	T	°C					l/min 20,5